
Scope


Design and built up The test runs Surface treatment Coating of the dipoles Summary of good & bad Conclusions

SPS-U meeting 2009-03-24


- August 2008: decision to coat MBA dipoles. Start studies for a coating system.
- September 2008: preliminary drawings. The design office suspend the work for three weeks due to an "urgent job".



- August 2008: decision to coat MBA dipoles. Start studies for a coating system.
- September 2008: preliminary drawings. The design office suspend the work for three weeks due to an "urgent job".
- October 2008: final MBA drawings. Launch fabrication.
 Bad results with parallel fields in lab tests. Search alternatives.
- November 2008: test new configuration with anodes: OK.
 Keep searching alternatives. SPS-U workgroup ask for
 MBB instead of MBA. New drawings. Launch fabrication.




- August 2008: decision to coat MBA dipoles. Start studies for a coating system.
- September 2008: preliminary drawings. The design office suspend the work for three weeks due to an "urgent job".
- October 2008: final MBA drawings. Launch fabrication. Bad results with parallel fields in lab tests. Search alternatives.
- November 2008: test new configuration with anodes: OK.
 Keep searching alternatives. SPS-U workgroup ask for
 MBB instead of MBA. New drawings. Launch fabrication.
- December 2008: test configuration with rectangular cathodes anodes: GOOD. Configuration retained for the prototypes. No time to produce new pieces: adapt the ordered ones.



- August 2008: decision to coat MBA dipoles. Start studies for a coating system.
- September 2008: preliminary drawings. The design office suspend the work for three weeks due to an "urgent job".
- October 2008: final MBA drawings. Launch fabrication.
 Bad results with parallel fields in lab tests. Search alternatives.
- November 2008: test new configuration with anodes: OK.
 Keep searching alternatives. SPS-U workgroup ask for
 MBB instead of MBA. New drawings. Launch fabrication.
- December 2008: test configuration with rectangular cathodes anodes: GOOD. Configuration retained for the prototypes. No time to produce new pieces: adapt the ordered ones.
- January 2009: mount system (assembling bench&vacuum)
- February 2009: adapt electrodes. Start tests and coatings.



- August 2008: decision to coat MBA dipoles. Start studies for a coating system.
- September 2008: preliminary drawings. The design office suspend the work for three weeks due to an "urgent job".
- October 2008: final MBA drawings. Launch fabrication.
 Bad results with parallel fields in lab tests. Search alternatives.
- November 2008: test new configuration with anodes: OK.
 Keep searching alternatives. SPS-U workgroup ask for
 MBB instead of MBA. New drawings. Launch fabrication.
- December 2008: test configuration with rectangular cathodes anodes: GOOD. Configuration retained for the prototypes. No time to produce new pieces: adapt the ordered ones.
- January 2009: mount system (assembling bench&vacuum)
- February 2009: adapt electrodes. Start tests and coatings.
- March 2009: installation of the three dipoles



4 test runs in liner

Main difficulties:

 Plasma unstable => run at high pressure (3.5x10⁻¹ mbar) non uniform magnetic field at extremities




4 test runs in liner

Main difficulties:

- Plasma unstable => run at high pressure (3.5x10⁻¹ mbar) non uniform magnetic field at extremities
- Ceramic washes for cathode isolation too thin (2 mm) => current leaks => change to ceramic spacers (7 mm)

Highly non uniform transversal thickness profile: ~10x thicker near the cathodes than at the center





4 test runs in liner

Main difficulties:

- Plasma unstable => run at high pressure (3.5x10⁻¹ mbar) non uniform magnetic field at extremities
- Ceramic washes for cathode isolation too thin (2 mm) => current leaks => change to ceramic spacers (7 mm)

Highly non uniform transversal thickness profile: ~10x thicker near the cathodes than at the center





4 test runs in liner

Main difficulties:


- Plasma unstable => run at high pressure (3.5x10⁻¹ mbar) non uniform magnetic field at extremities
- Ceramic washes for cathode isolation too thin (2 mm) => current leaks => change to ceramic spacers (7 mm)


Highly non uniform transversal thickness profile: ~10x thicker near the cathodes than at the center

• During the 4 runs several modifications were introduced. Anodes configuration, isolation, geometry at extremities, thermocouples, etc.

The possible modifications regarding the time available...

• After the 4th run no more time for tests => COAT DIPOLES





Coating of the three dipoles

Surface treatment:

- Control before surface treatment: hydrocarbons and silicon contamination.
- Procedure:
 - 1. Brush with acetone
 - 2. Rinse with demineralized water
 - 3. "lessive" Galvex (for Silicon contaminations)
 - 4. "lessive" P3 Almeco (for hydrocarbons)
 - 5. Rinse with demineralized water
 - 6. Dry by air flow
- Results: ok for silicon; but remain traces of hydrocarbons

"Les résultats ne sont pas brillant, forte présence de particules métalliques et de produit hydrocarbonés (sans surprise). Par contre, présence de produits silicones..."

Report N° VSC-CSA : X-02/01.09 by B. Teissandier



Coating of the three dipoles

Surface treatment:

- Control before surface treatment: hydrocarbons and silicon contamination.
- Procedure:
 - 1. Brush with acetone
 - 2. Rinse with demineralized water
 - 3. "lessive" Galvex (for Silicon contaminations)
 - 4. "lessive" P3 Almeco (for hydrocarbons)
 - 5. Rinse with demineralized water
 - 6. Dry by air flow
- Results: ok for silicon; but remain traces of hydrocarbons
- The mysterious "white spots" are not removed by the surface treatment.

"Les résultats ne sont pas brillant, forte présence de particules métalliques et de produit hydrocarbonés (sans surprise). Par contre, présence de produits silicones..."

Report N° VSC-CSA : X-02/01.09 by B. Teissandier






Coating of the three dipoles

Coating:

• Parameters:

Pressure between $3.0x10^{-1}$ and $3.9x10^{-1}$ mbar Power ~ 2kW Voltage ~ 900 V Temperature on the side of the chamber ~ 120 °C

- Thickness: the same non uniformity of the test runs: ~200 nm at the center, ~1500 nm near the cathodes.
- Endoscopy after coating only possible in MB096: no evidence of peel-off .
- Storage after coating: 1.2 bar of N₂
- SEY after coating = 1.0
- SEY just before pump down in the tunnel = 1.0
- During installation in the tunnel <u>PEEL-OFF</u> observed in MB085! (only ~ 1 cm²... but always scaring!)



Good&Bad: the coating itself

BAD

GOOD

Too non uniform thicknessNot all the length is coated (95%)

•SEY around 1 •Ageing (... so far...)

Good&Bad: the coating process

BAD

- •Plasma quite unstable! (not reliable)
- •Isolation system need to be changed every run
- •Thermal deformation of the anodes
- •Deposition time too long (34 hours)
- •Wheels sliding, not rolling! (dusty)

•Temperature monitoring not allows displacement of the electrodes

GOOD

- •Fast mounting/dismounting (if not necessary to change isolation)
- •Easy to control the coating pressure
- •Potential for a large scale production.

But the electrodes have to be modified

SPS dipole prototype coatings Modifications

•drive the plasma independently at the extremities => *increase stability, decrease pressure, improve thickness profile and adhesion, decrease coating time.*

•Shield the bottom and top of the cathodes => *increase stability, improve thickness profile and adhesion.*

•Use ceramic screws for the cathodes supports => *faster mounting/ dismounting.*

•Introduce stainless steel plate between the back of the cathode and the ceramic isolation => *avoid current leaks due to graphite "dust", improve reliability.*

•Modify the anodes system to avoid thermal deformation => *increase stability, improve thickness profile and adhesion.*

•Decrease distance between cathodes? (40mm) => *improve thickness profile and adhesion, decrease coating time, decrease outgassing of the chamber, allow higher power?*

•Change the temperature monitoring system => *compatible with the displacement of the electrodes.*

SPS dipole prototype coatings Conclusions

•The system is not so bad... but it is not good enough!... Yet.

•Good SEY and ageing but the peel-off observed with the dipoles already in the tunnel is scaring.

•Modifications towards *thickness uniformity*, *stability of the discharge* and *reliability of the electrodes isolation*

•Re-think surface treatment

•Start studying the piling-up of coating systems?

•Prepare liners to be coated inside the dipoles and tested in the SPS?

First test run on the 10th *February, dipoles installed the* 10th *March.*

It was intense, stressing, but very pleasant.